# Oil Field Environmental Incident Summary

Responsible Party: Polar Midstream, LLC

Well Operator:

Well Name: Stampede Mainline Valve Set 5

Field Name: Well File #:

Date Incident: 3/18/2016 Time Incident: 12:04 Facility ID Number:

County: DIVIDE Twp: 162 Rng: 95 Sec: 16 Qtr: SW SW

Location Description: A crude oil spill occurred at the Stampede Mainline Valve Set 5 located in

Divide County. The coordinates of the incident are 48.85109, -103.02299.

The nearest cross streets are 108th Ave NW and 99th St. NW.

Submitted By: Andrew Parisi Received By:

Contact Person: Andrew Parisi

5831 123rd Drive NW Epping, ND 58843

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 4.7 Barrels

**Brine** 

Other

Description of Other Released Contaminant:

N/A

Inspected: Written Report Received: Clean Up Concluded:

### Risk Evaluation:

No impact or potential to impact surface waters. No threat to the public.

# Areal Extent:

The estimated aerial extent of the spill is 30 ft by 70 ft extending southeast from the valve set.

# Potential Environmental Impacts:

The pipeline leak impacted the soil on the valve set location and southeast toward 99th St NW. The impacted soil will be excavated and removed from the location. No impact or potential to impact any surface waters.

## Action Taken or Planned:

The landowner notified Polar Midstream, LLC operations on 3/18/2016. Field Operations were immediately dispatched to the area, confirmed the leak, and shut the valve below the pressure gauge to stop the leak on 3/18/2016 at 12:04 pm CST. Polar Midstream immediately contacted a remediation contractor and they were dispatched to the site to recover any standing oil and begin remediating the site. Polar Midstream also notified the Divide County Sherriff's Department of the vandalism and filed a report with the Sherriff's deputy on 3/18/2016.

**Wastes Disposal Location:** Recovered waste and impacted soil will be hauled to a licensed disposal facility in the area.

Agencies Involved: Local Law Enforcement

# **Updates**

Date: 3/18/2016 Status: Reviewed - Follow-up Required Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

### Notes:

According to the report, 4.7 barrels of oil from a pipeline leak impacted cultivated soils. Further followup needed.

Date: 3/22/2016 Status: Inspection Author: O'Gorman, Brian

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

Arrived on location at 16:45. East wind 15-25 mph, cloudy, 21 degrees F. Met with the contractor on site who let me know that they had removed approximately 80 tons of impacted soils from the area and were still delineating the extent. The excavation was approximately 60 feet in diameter and 10 feet deep near the pipeline. Some excavated soils remained on plastic sheeting next to the hole and were supposed to be removed today. Photos were taken of the excavation and surrounding area. More follow-up will be needed.

Date: 3/30/2016 Status: Inspection Author: Kangas, Kathleen

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

# Notes:

On site at 12:00 p.m. Cloudy, 43 degrees F, wind 10 mph ENE. Large hole has been excavated extending east of the valve. No leaking apparent. Some oil odor. Soil is piled up around excavated hole. Equipment is on site, including some side dump trucks. No personnel on site. Follow-up needed.